

Notes These Causes of Motor Failure

Efficient Plant
535 Plainfield Road, Suite A
Willowbrook, IL 60527

Ph: 630.325.2497

www.efficientplantmag.com
email: editors@atpnetwork.com

First published in the October 2017 issue of *Efficient Plant* magazine

Brushing up on Important Root Causes Now can Prevent Headaches Later

Winding insulation breakdown and bearing wear are the two most common causes of motor failure, but they arise for many different reasons. Based on information in a recently released “Application Note” from Fluke (fluke.com, Everett, WA), the following list highlights the 13 most common causes of failure in winding insulation and bearings.

Read more. . .

<https://www.efficientplantmag.com/2017/10/note-causes-motor-failure/>